

TEST REPORT



REPORT NO.: CTNT230423012

Product name: Vision Rehabilitation Instrument

Model No.: sky-n1201a

Applicant: BEIJING MINGRENSHIKANG SCIENCE&TECHNOLOGY Co., Ltd

Test procedure: Entrustment Test

Shenzhen Zhongwei Testing Technology Co., Ltd.



This report may not be reproduced in part without permission to avoid ambiguous interpretation.

This report can be checked and verified in the following ways.

Tel: 0755-28680489

E-mail: admin@ctnt-cert.com

Web: www.ctnt-cert.com

TEST REPORT

IEC 60825-1

**Safety of laser products – Part 1:
Equipment classification and requirements**

Report Number.....: CTNT230423012

Date of issue.....: Jun 1, 2023

Name of Testing Laboratory preparing the Report.....: Shenzhen Zhongwei Testing Technology Co., Ltd.
Room 1A106, 1/F., No.109, Lijia Road, Henggang, Henggang Street, Longgang District, Shenzhen, Guangdong, China
Tel: 086-13662574496
E-mail: admin@ctnt-cert.com
Web: www.ctnt-cert.com

Applicant's name.....: BEIJING MINGRENSHIKANG SCIENCE&TECHNOLOGY Co., Ltd
Address.....: 401-6Room, 21 Torch Street, Science and Technology Park, Changping District

Manufacturer's name.....: BEIJING MINGRENSHIKANG SCIENCE&TECHNOLOGY Co., Ltd
Address.....: 401-6Room, 21 Torch Street, Science and Technology Park, Changping District

Test specification:

Standard.....: IEC 60825-1: 2014

Test procedure.....: Entrustment Test

Non-standard test method.....: N/A

Test Report Form No.....: IEC 60825_1E

Test Report Form(s) Originator.....: CTNT

Master TRF.....: Dated 2021-04-19

General disclaimer:

The test results presented in this report relate only to the object tested.
This report shall not be reproduced, except in full, without the written approval of the Issuing CTNT Testing Laboratory.
The authenticity of this Test Report and its contents can be verified by contacting the CTNT, responsible for this Test Report.

Test item description.....: Vision Rehabilitation Instrument

Trade Mark.....: N/A

Model/Type reference.....: sky-n1201a

Ratings.....: 6V ==

This report may not be reproduced in part without permission to avoid ambiguous interpretation.

This report can be checked and verified in the following ways.

Tel: 0755-28680489

E-mail: admin@ctnt-cert.com

Web: www.ctnt-cert.com

Responsible Testing Laboratory (as applicable), testing procedure and testing location(s):		
Laboratory Name	Shenzhen Zhongwei Testing Technology Co., Ltd.	
Testing location/ address..... :	Room 1A106, 1/F., No.109, Lijia Road, Henggang, Henggang Street, Longgang District, Shenzhen, Guangdong, China	
Tested by(Test Engineer)..... :	Rock Zhou	
Reviewed By(Supervisor)..... :	Airan Lu	
Approved by(Chief Engineer)..... :	Flight Lee	
List of Attachments (including a total number of pages in each attachment):		
<ul style="list-style-type: none"> - Photo document - Test data graph 		
Summary of testing:		
Tests performed (name of test and test clause):	Testing location:	
Determination of the result includes consideration of measurement uncertainty from the test equipment and methods.	Shenzhen Zhongwei Testing Technology Co., Ltd.	
According to the test of IEC 60825-1: 2014	Room 1A106, 1/F., No.109, Lijia Road, Henggang, Henggang Street, Longgang District, Shenzhen, Guangdong, China	
Safety of laser products – Part 1:	Tel: 086-755-28680489	
Equipment classification and requirements.	E-mail: admin@cnt-cert.com	
This product complied with the requirements of Class 1.	Web: www.cnt-cert.com	
Test item particulars..... :		
Supply Connection..... :	Battery-powered	
Possible test case verdicts:		
- test case does not apply to the test object..... :	N/A	
- test object does meet the requirement..... :	P (Pass)	
- test object does not meet the requirement..... :	F (Fail)	
- test object does not experiment with this clause.:	-	
Testing..... :		
Date of receipt of test item..... :	April 23, 2023	
Date (s) of performance of tests..... :	May 4, 2023	

